Approved For Release 2003/12/23 : CIA-RDP33-02415A000300150047-0 IDEA-0659

Cy 3 of 3

7 February 1962

SUBJECT: Monthly Commander's Report	
To: Chief, DID	
1. Naturally the big news of the month was getting Tackled off the Reedlers to say this has created much enthusiaem among the troops from be sides and we were all very dissappointed when the subsequent missions we cancelled. We have taken aggressive action to work out any deficiencies our SIRT duping procedures and our prompt delivery of the take. With a available to us it appears that we can meet a very satisfactory military schedule for every mission except those run on Saturdays. On a Saturday it appears that COMMAIR would be necessary for prompt delivery. This day the only period where we have a wide schedule gap and unfortunately we into it on our first mission.  Appeared vary satisfied with time element regarding the return take however. In case of emergency whould be the possibility of sending the C-130 all the way to Hawaii?  2. I have eliminated the local ODURIT weather and intelligence supply which was established prior to my arrival. I have done this for two real first it falls more in line with our cover story to make this a complete show. Secondly can provide me with better products in both these and I feel that it eliminates a lot of superfluous personnel and actions As you know we are going through the Badlands at a relatively lon 352. Hy only concern here is that your planners take this interesting a lot of scraable activity from our training missions and I they will be pretty jumpy the next run. The new (358) gives a governormance (right by the book).  8. Administration  1. Personnel Movements during January:	oth re in C-130 air mission is in the it ort sons.  areas ov ET ortration ve have believe

25X1A

25X1A 25X1A

25X1A

25X1A

25X1A

Approved For Release 2003/12/23 : CIA-RDP33-02415A000300150047-0

5X1A				
4. Tot	ol evranditur	es for Janus	ry 1962 were	 Breakdown 25

25X1A

25X1A 25X1A were training missions, three test flights, and one operational mission. A total of 68:40 hours were flown. Three flights were cancelled. One due to weather, one for an early engine change ordered by Headquarters, and one due to maintenance. The operational mission was a success, and no unusual problems were encountered. Three flame-outs were experienced. Two were by on training thick test flight.

Cause was attributed to extremely low tolerance of the engine-airframe combination while operating in the "Badlands" area.

- 2. The T-33 was flown a total of 51:40 hours. Training was accomplished as outlined in Attachment 2.
- 3. Three Pilots' Meetings were held. The Operational Mission was discussed at length by the \_\_\_\_\_\_ who flew it. Emergency procedures were reviewed with all pilots. Navigation procedures and flight line following techniques were discussed.
- 4. The Flight Planning Section reviewed all maps to insure availability of latest publications. Three new Training Missions were planned, to establish a firm fuel curve for 352. The data was reduced and forwarded to Hqs.
- 5. The Photo Interpreter continued close lisison with and instruction of indigenous F.I.'s.

# D. Material

- 1. New Supply Warehouseman arrived 7 January. Materiel Officer highly pleased with this individual's qualifications and initial enthusiasm for his assignment. Subject is learning the details of the job functions very quickly. On 12 January, the Supply Stock Records Technician departed from this station for the ZI.
- 2. Materiel problems appeared during this period but all were within local capability to correct. Logistic support by the Zl Project Depot continued at its customary high effectiveness. Several projects of an internal nature in the Supply Section involving inventories of FAK and SLOE items and the physical inspection of all on-shelf items for "out-of-date" or expired shelf life expectancy factors continued through this period.

#### E. Maintenance

- 1. Aircraft time at end of month is 1654.05.
- on 18 January engine installation was complete and \_\_\_\_\_ was tied down for trim run. Trim run turned out good except for one fuel leak at the outlet side of the fuel totalizer. Internal "O" ring replacement on fitting proved successful for repair of leak and no further trouble was encountered. Test flight was made on 19 January for duration of 2:30. There were three minor pilot write-ups on this flight. On the two successive flights after test flight, the drivers experienced engine flame-outs while climbing through the Badlande. Two more flights were made using same flight schedule but at a lower EST setting. These flights turned out successfully, so upon the advise of the \_\_\_\_\_ technical representative and pilot agreement this new lower EST setting was set up as the standard procedure for A/C and engine penetrating

25X1A

25X1A

25X1A

25X1A

25X1A

the Badlands. 26 January sortie of 7:40 flown and had further trouble. Pilot on this flight reported he was unable to get proper EST, RPM, or fuel flow at full throttle. It seemed apparent that we were encountering further trouble with the fuel control. 27 January replaced fuel control with the original fuel control and made trim run. Test flight of 7:40 made using the lower EGT setting as previously agreed upon. Flight turned out with good results. No further fuel control problems have been encountered to date.

25X1A 25X1A

25X1A 25X1A

25X1A

F. Security
l. New commissary and BX cards were received during the month. All persons assigned to now have commissary privileges.
3. On 26 January IDENTITY P spent a full afternoon visiting our activity. He is the top military man in He appeared very interested in our operation and observed the recovery of a from a training mission.
G. Personal Equipment
1. The Personal Equipment Section instructed all pilots in the use of the MD-1 seat pack, and the RES-Q-PAK life preserver was demonstrated.
2. An aluminum shield of local manufacture was installed on all Q207 seat packs. Its purpose is to protect the oxygen systems from damage by the weight of the survival equipment.
H. Special Equipment
1. All personnel have completed their annual leave and the Section is at full strength.
2. Four missions were flown during the month, total film footage: 37,440. Mission HT-62-17 had a shutter malfunction for 280 feet. This malfunction appears to have been caused by the intermittent failure of an electri-

## 1. Installations

The only major construction item this month was an office for the Materiel Supervisor. This was constructed by adding a small room to the outside of the Hangar area and I believe that it will increase the already efficient operation of this section.

cal relay in the programmer and not by the shutter. When investigation of

trouble is completed the parts will be replaced.

IDEA-0659 Cy 3 of 3

5

# J. Communications

- 1. In preparing the ELINT take from our first operational mission the shortcomings of the procedures for preparing the take for shipping and the duping procedures were exposed. Technical feed-back, corrective measures and other details have been exchanged with Headquarters by cable. The duping equipment is now in relative good condition and with the arrival of an additional duping rack and a review of procedures it is believed that the procedures and minimum time requirements laid down by Headquarters can be met.
- 2. Considerable work was done on cleaning up the telephone system at both the Hostel and Hangar. All field lines have been replaced with standard rubber drop cables. An eighteen pair cable has been run into the Hangar. This takes care of present requirements and leaves six spare pairs. There are at present three hot lines installed from the Hangar to Hestel, Hangar to BOQ and 25X1A Hangar to weather building.

### Attachments:

- 1. Summary of January 1962 Expenditures, in dupl, h/w
- 2. Flying Accomplishment Chart, 1 copy, h/w
- 3. Identities, in trip, u/s/c

#### Distribution:

0 & 2, Hdqs, w/atts as stated

25X1A